

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:				
OGM	Pete Hess Environmental Scientist III			
Company	Mark Reynolds Resident Agent			

Inspection Report

Permit Number:	C0150025		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, February 03, 2005		
Start Date/Time:	2/3/2005 10:05:00 AM		
End Date/Time:	2/3/2005 11:25:00 AM		
Last Inspection:	Wednesday, January 12, 2005		

Inspector: Pete Hess, Environmental Scientist III

Weather: Clear; 30's F.

InspectionID Report Number: 524

Accepted by: whedberg 2/27/2005

Permitee: **CO-OP MINING CO**Operator: **CO-OP MINING CO**

Site: **BEAR CANYON MINE**

Address: PO BOX 1245, HUNTINGTON UT 84528

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

3,336.18	Total Permitted	✓ Federal	✓ Underground
36.64	Total Disturbed	☐ State	Surface
	Phase I	☐ County	Loadout
	Phase II	✓ Fee	Processing
	Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee continues to meet the requirement mandated by the Special Permit Condition included as Attachment "A" of the current State permit, (to submit surface and ground water monitoring information to the Division web site in an electronic form).

Inspector's	Signature
-------------	-----------

Date

Thursday, February 03, 2005

Pete Hess, Environmental Scientist III Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Thursday, February 03, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing	✓			
16.	o Roads: Drainage Controls	✓			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Thursday, February 03, 2005 Page 3 of 3

4.a Hydrologic Balance: Diversions

The majority of the site's diversions remain under frozen compacted snow. Very little melting has occurred since the last inspection, particularly in the right fork of Bear Creek (access road to the #3 and #4 Mines).

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Pond "B" was frozen over and snow convered. Pond "D" had a snow covered bottom. There were no compliance issues visible at either pond.

8. Noncoal Waste

There are three vehicles being parted out at the shop location on an as-needed basis. Mr. Reynolds was aware that this issue has been a concern to the Division in the past. He agreed to speak to Shop personnel to see if the vehicles could be sold as scrap, or removed from the Mine site.

9. Protection of Fish, Wildlife and Related Environmental Issues

The location in Bear Creek where the overhead mine conveyor crosses was checked for coal spill accumulation. Bear Creek was frozen and snow covered; flow was not audible. These was no coal accumulation visible.